




1/3/2019 Page 1 of 8





1/3/2019 Page 2 of 8

TOOLS REQUIRED









1/3/2019 Page 3 of 8

PRODUCT SPECIFICATIONS

B6WBCC CASCADES BENCH WITH BACK

Seats: 2x4 planks are made from a minimum of 96% post-consumer or post-industrial recycled plastic. Contains UV stabilizers to prevent fading. Seat support frame is made of 7 ga steel plate. Electrically MIG welded.

Frame: Legs are cast aluminum.


Frame Coating: Oven fused functionalized polyethylene copolymer-based thermoplastic. Fluidized bed coating application with superior mechanical performance, impact resistance and UV-stability.

Hardware: All fasteners are stainless steel.

Dimensions: 6' portable/surface mount bench with back. Seats are 18" wide x 72" long. Seat height is 19-1/4" from the ground to the top of the seat. The overall dimensions are 76" x 26-3/4" x 35-3/4".

1/3/2019 Page 4 of 8


COMPONENTS



ITEM NO. **PartNo** 11-01-CAST3 2 T-01-01-0246 954/964 recycled 6' seat support 2 x 4 Brown Recycled Bench Bullnose Plank-Lag Bolts (6'),
2 X 4 Cedar Recycled Bench Bullnose Plank-Lag Bolts (6'),
2 x 4 Green Recycled Bench Bullnose Plank-Lag Bolts (6'),
or 2 x 4 Grey Recycled Bench Bullnose Plank-Lag Bolts (6'),
2 x 4 Brown Recycled Bench Plank-Lag Bolts (6'), 2 X 4
Cedar Recycled Bench Plank-Lag Bolts (6'), 2 x 4 Green
Recycled Bench Plank-Lag Bolts (6'), or 2 x 4 Grey Recycled
Bench Plank-Lag Bolts (6') BRN72-2x4B-LB, CDR72-2x4B-LB, 3 2 GRN72-2x4B-LB, or GRY72-2x4B-LB BRN72-2x4-LB. CDR72-2x4-LB, 6 GRN72-2x4-LB, or GRY72-2x4-LB 5 33-02-0007 5/16" SS Washer 4 6 33-06-0053 5/16" x 2-1/4" Carriage Bolt (SS) 4 5/16" Kep Nut (SS) 7 33-03-0012 4 5/16" x 1-1/4" lag bolt, SS 8 33-05-0034 24 25 33-02-0008 3/8" Flat Washer (SS)


Optional Surface Mount Hardware: 3/8" x 3-1/2" Concrete Expansion Anchor Bolts (Not Included)

1/3/2019 Page 5 of 8



1/3/2019 Page 6 of 8


STEP 2



Attach the 6' Recycled Bench Planks to the Seat Support, placing the 2 Bullnose Planks on the outside, as shown using specified hardware.

Warning: Over tightening of the Lag Bolts may result in cracking and/or stripping out of the Planks.

1/3/2019 Page 7 of 8



1/3/2019 Page 8 of 8